



# Installation Instructions





## PROFESSIONAL GRECATO AND GRECATO LARGE CLADDING INSTALLATION






Fastening of joists with maximum center distance of 40 cm.




Install the corner start profiles and the terminal.



Start the cladding installation.



Continue the installation up to the corner.



Complete installation.

